
Feb_25_2020_06-09-11-PM

VIN retrieved from vehicle

VIN: 1HGCM72317A023083

Vehicle: 2007 Honda Accord

Odometer: 75,915 mi

1 Confirmed Trouble Codes:

- P0420: Catalyst System Efficiency Below Threshold Bank 1 - Catalyst System Efficiency Below Threshold Bank 1
-

0 Pending Trouble Codes:

1 Antilock Braking System Trouble Codes:

- 61: Power supply voltage failure information: Low or High Voltage
-

1 Engine Trouble Codes:

- 67-01: Catalyst System Efficiency Below Threshold/[Bank 2] - No description available
-

3 Relay Module Trouble Codes:

- B1055: Lost Communication with MICU (MICU frame) - Relay control module lost communication with MICU
 - B1056: Lost Communication with MICU (ALARM frame) - Relay control module lost communication with MICU (alarm message)
 - B1057: Lost Communication with MICU (DOORSW frame) - Relay control module lost communication with MICU (door switch message)
-

2 Power Window Module Trouble Codes:

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

-
- B1105: Lost communication with MICU (DOORSW frame) - Door Multiplex Control unit lost communication with MICU (Door switch message)
 - B1106: Lost communication with MICU (MICU frame) - Door Multiplex Control unit lost communication with MICU (MICU message)
-

2 Meter Module Trouble Codes:

- B1157: Lost Communication With MICU (MICU frame) - Gauge control module lost communication with the MICU (MICU message)
 - B1159: Lost Communication With MICU (DOORSW frame) - Gauge control module lost communication with the MICU (DOORSW message)
-

1 Combination Switch Module Trouble Codes:

- B1255: Lost communication with MICU (MICU frame) - Combination Switch Control Unit lost communication with MICU
-

Vehicle Protocol: ISO_9141

Sensor F/W Version: v2.58

App Version: 7.1.3-b224

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.